




PROJECTS

CONTAMINATED LAND & GROUNDWATER

PRELIMINARY and LIMITED PHASE 2 SITE INVESTIGATION  
Steam Laundry Facility in Perth's Suburbs

HydroSolutions Pty Ltd undertook a Preliminary Site Investigation (PSI) and subsequently a limited phase 2 investigation at a Steam Laundry Facility in Perth's suburbs.

Although no contaminating activity was identified in the PSI, leaching and/or spillage of materials entering adjacent unsealed soakwells were identified as potential contaminant pathways.



Results of the Limited Investigation indicated that:

- Run-off received in the soakwell was impacted by site operations.
- The presence of specific contaminants used in site operations in bore water suggested that the site operations have a low but measurable impact on groundwater quality beneath the site.
- Effluent quality from the underground storage tank was within the relevant 'waste water acceptance criteria'.

It was concluded that a full Detailed Site Investigation (DSI) was not warranted.

HydroSolutions Pty Ltd  
U14/14 Whyalla Street  
Willetton  
Western Australia 6155  
Tel: (+61 8) 9457 5448  
Fax: (+61 8) 9457 4293  
Mob: 0403 021533

E-mail: [stuart.jeffries@hydrosolutions.com.au](mailto:stuart.jeffries@hydrosolutions.com.au)  
Website: [www.hydrosolutions.com.au](http://www.hydrosolutions.com.au)