



PROJECTS

CONTAMINATED LAND & GROUNDWATER

Contam 3

HARD CHROMING & ENGINEERING PLANT, Welshpool, WA

Investigation of site conditions



A stage 1 & 2 review of site conditions at a hard-chroming and engineering works located in Welshpool, WA was undertaken.

Soil & groundwater concentrations were compared to health-based guidelines and recommendations were made for suitable remedial works for the on-going industrial operation.

Recommendations were also made for the disclosure of site conditions to regulatory authorities, and increased groundwater monitoring at the company's existing and newly acquired sites.

HydroSolutions Pty Ltd  
U14/14 Whyalla Street  
Willetton  
Western Australia 6155  
Tel: (+61 8) 9457 5448  
Fax: (+61 8) 9457 4293  
Mob: 0403 021533

E-mail: [stuart.jeffries@hydrosolutions.com.au](mailto:stuart.jeffries@hydrosolutions.com.au)  
Website: [www.hydrosolutions.com.au](http://www.hydrosolutions.com.au)